I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to:

Commissioner for Patents

United States Patent & Trademark Office Attention: Certificate of Correction Branch

P.O. Box 1450

Alexandria, VA 22313-1450, on

DATE

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Examiner: Derek Boles

Certificate

Group Art Unit: 3749

MAR 0 3 2005

In re application of

of Correction

Larry Dwight Robinson

: VENT WITH PRESECURED

: MECHANICAL FASTENERS

Serial No. 10/600,397

Filed: June 20, 2003

Patent No. 6,793,574 B1

Issued: September 21, 2004

: ATTORNEY DOCKET: 282496-00146

LETTER

600 Grant St., 44th Floor Pittsburgh, PA 15219 February 21, 2005

Commissioner for Patents United States Patent & Trademark Office Attention: Certificate of Correction Branch P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

In comparing the above-identified original patent document with the original papers filed in the Patent and Trademark Office, we have noted five (5) errors which were the printer's errors. There are also two (2) typographical errors which should be

02/25/2005 FMETEKI2 00000004 022556 6793574

01 FC:1811

100.00 DA

charged to our Deposit Account No. 02-2556 in the amount of One Hundred Dollars (\$100).

It is respectfully requested that a Certificate of Correction be issued to correct these printing errors in the above-identified patent.

(412) 566-2077

Respectfully submitted,

Arnold B. Silverman

Registration No. 22,614

Attorney for Applicant

MAR 0 4 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. :

6,793,574 B1

DATED

September 21, 2004

INVENTOR(S):

Larry Dwight Robinson

It is certified that errors appear in the above-identified patent and that said Letters Patent should be corrected as shown below:

Col. 2, line 52, "filly" should read --fully--.

Col. 4, line 28, "modifications. provided", should read --modifications provided--.

Col. 4, line 45, "110,112" should read --110, 112--.

Col. 4, line 46, "122,126" should read -- 122, 126--.

Col. 5, line 36, "maybe" should read -- may be--.

Col. 8, line 30, "passageway" should read --passageways--.

Col. 8, line 38, "passageway" should read --passageways--.

1 of 1

MAILING ADDRESS OF SENDER:

Sally Novosel, Docket Administrator ECKERT SEAMANS CHERIN & MELLOTT, LLC 600 Grant Street, 44th Floor Pittsburgh, PA 15219 **PATENT NO. 6,793,574**

No. of add'l. copies @ 50¢ per page

